MARYLAND HISTORICAL TRUST DETERMINATION OF ELIGIBILITY FORM

NR Eligible: yes _____ no _______

Property Name: Saint John's Evangelical Lutheran Church	Inventory Number: BA- 866
Address: 8808 Harford Road (MD 147)	Historic district: yes X no
City: Parkville Zip Code: 21234	County: Baltimore County
USGS Quadrangle(s): Towson	
Property Owner: Saint John's Evangelical Lutheran Church Ta	ax Account ID Number: 0919000670
Tax Map Parcel Number(s): 606 Tax Map Number	: 71
Project: MD-147 Parkville Streetscape Project Agency:	SHA
Agency Prepared By: EHT Traceries	
Preparer's Name: Krista Gebbia	Date Prepared: 5/2/2006
Documentation is presented in:	
Preparer's Eligibility Recommendation: Eligibility recommended	X Eligibility not recommended
Criteria: A B C D Considerations: A B	CDEFG
Complete if the property is a contributing or non-contributing resource	to a NR district/property:
Name of the District/Property:	
Inventory Number: Eligible: yes	Listed: yes
ite visit by MHT Staff yes X no Name:	Date:
Description of Property and Justification: (Please attach map and photo)	
Constructed in the Gothic Revival style, St. John's Lutheran Church dates to a mid-cast side of Baltimore City. This stretch of Harford Road was already developing at Office, in which the church was erected, was a thriving community. With the growt community of Lavender Hill has become a suburb of the city and the surrounding buperiod of development. The stone church was constructed in the Gothic Revival style style of architecture in the mid-20th century. The Gothic Revival style abstracted el Europe, primarily those of England and France. Representative of this style are the buttresses.	t a fast pace by 1850, and Lavender Hill Post h and expansion of Baltimore City, the nilt environment indicates this mid-20th century le and represents a resurgence of interest in this ements from Gothic cathedrals of medieval
Although associated with the rapid population growth and suburbanization trend in following the expansion of the streetcar line in 1918, and then following World War is not the best or earliest illustration of this growth and therefore does not qualify for not associated with any person or group of persons of outstanding importance to the property is not eligible under Criterion B. The church is typical of mid-20th-century	r II, Saint John's Evangelical Lutheran Church r eligibility under Criterion A. The property is community, state, or nation. Therefore, the
MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended Eligibility not recommended >	
Criteria: A B C D Considerations: A	B _ C _ D _ E _ F _ G
MHT Comments:	
Beuty 7/	7/11/06 Date
Reviewer, National Register Program	Date

BA- 866

Page 2

County. Therefore, Saint John's Evangelical Lutheran Church does not qualify for eligibility under Criterion C. The property was not evaluated under Criteria Consideration D. In addition, the church and the cemetery were evaluated under Criteria Consideration A (Religious Properties) and Criteria Consideration D (Cemeteries). As typical example of a mid-20th-century Gothic Revival-style church, Saint John's Evangelical Lutheran Church is not exemplary for its architectural or artistic distinction, nor does it possess exceptional historical importance because it was associated with an important non-religious event or significant religious event. The chruch currently serves as a religious structure, not as an investment property. Saint John's Evangelical Lutheran Church Cemetery does not possess the markers of significant persons, exhibit distinctive design features, nor is it associated with any noteworthy historic events. Therefore, Saint John's Evangelical Lutheran Church is not eligible under Criteria Consideration A and the Saint John's Evangelical Lutheran Church Cemetery is not eligible under Criteria Consideration D.

This Gothic Revival church, built circa 1950, fronts southeast with a cemetery and a paved parking lot to the north. The random, ashlar-cut stone foundation supports a random Ashlar-cut stone structural system. Standing one-and-a-half stories tall and three bays wide, the church has a front gable roof with slate tiles and a parged concrete chimney on the exterior end. In the gabled parapet of the façade is a stained glass, pointed arch window with wood tracery placed above three, grouped pointed-arch stainedglass windows. The spandrel between the windows consists of stone quatrefoils. The windows have molded wood surrounds, a pointed-arch stone lintel, and stone sills. Flanking this large window are two, pointed-arch stained-glass windows with metal, diamond panes and stone surrounds. Projecting to the east are two wings, the smaller of which contains the main entry. The entry features two paneled double-leaf doors made with beaded vertical board. Each set of doors has wood surrounds, a pointed-arch. stone lintel, and a molded, stone tympanum. In the gable end of the wing's parapet is a metal, louvered vent with stone surrounds. In the hyphen connecting the two wings are three stained glass metal windows rectangular in shape that are grouped with a stone lintel containing three, pointed arches. The larger wing has eight paired 1/1 windows with square-edged wood surrounds, stone sills, and jack arch, stone lintels on the southeast elevation. Differences in building materials suggest that the main block was built in two stages with an additional four-bays in depth added to the original four bays. The southwest elevation of the original church has a random, Ashlar-cut stone belfry projecting from the roof in a gabled parapet. Including all eight bays of the main block and the addition, there are seven stained-glass metal windows rectangular in shape with stone surrounds, sills, and lintels. Also, there are twelve 1/1 windows with square-edged wood surrounds and stone lintels and sills. There are three flush metal doors that are single-leaf with one-light and molded wood surrounds. The rear of the addition is parged concrete with three pointed-arch stained glass windows grouped in a large pointed-arch stone lintel with parged concrete spandrels and stone sill.

Located to the north of the church is a cemetery enclosed in a chain link fence. Surveyed from the parking lot, the cemetery appears to have approximately thirty-two rows of 200 headstones facing southeast. These mostly upright granite and marble markers range in date from 1833 to 2000. Some of the family names within this sloping cemetery are Maria, Foard, Dorr, Geddis, and Todd.

Located to the northwest of the church are offices in the Smith Building built circa 1960. This one-story building clad in stucco has a hipped roof with asphalt shingles. There is an exterior-end parged chimney and a vinyl, 1/1 window with vinyl surrounds and a parged sill. The building features three entrances: two flush single-leaf doors made of metal and a double-leaf metal door that is flush with lights.

MARYLAN Eligibility re					gibility not recommend	ded						
Criteria:	A ments:	В	C	D	Considerations:	A	В	C	D	E	F	G
	Reviewe	er, Office	e of Pres	servatio	on Services			Date				

CAPSULE SUMMARY
BA- '866
St. John's Evangelical Lutheran Church
8808 Harford Road
Baltimore, Baltimore County
1950 ca.
Public

Constructed in the Gothic Revival style, St. John's Lutheran Church dates to a mid-20th century period of suburbanization on the east side of Baltimore City. This stretch of Harford Road was already developing at a fast pace by 1850, and Lavender Hill Post Office, in which the church was erected, was a thriving community. With the growth and expansion of Baltimore City, the community of Lavender Hill has become a suburb of the city and the surrounding built environment indicates this mid-20th century period of development. The stone church was constructed in the Gothic Revival style and represents a resurgence of interest in this style of architecture in the mid-20th century. The Gothic Revival style abstracted elements from Gothic cathedrals of medieval Europe, primarily those of England and France. Representative of this style are the building's pointed-arch windows and wall buttresses.

This church fronts southeast with a cemetery and a paved parking lot to the north. The random, ashlar-cut stone foundation supports a random Ashlar-cut stone structural system. Standing one-and-a-half stories tall and three bays wide, the church has a front gable roof with slate tiles and a parged concrete chimney on the exterior end. In the gabled parapet of the façade is a stained glass, pointed arch window with wood tracery placed above three, grouped pointed-arch stained-glass windows. The spandrel between the windows consists of stone quatrefoils. The windows have molded wood surrounds, a pointed-arch stone lintel, and stone sills. Flanking this large window are two pointed-arch stained-glass windows with metal, diamond panes and stone surrounds. Projecting to the east are two wings, the smaller of which contains the main entry. The entry features two paneled double-leaf doors made with beaded vertical board. Each set of doors has wood surrounds, a pointed-arch, stone lintel, and a molded, stone tympanum. In the gable end of the wing's parapet is a metal, louvered vent with stone surrounds. Differences in building materials suggest that the main block was built in two stages with an additional four-bays in depth added to the original four bays. Located to the north of the church is a cemetery enclosed in a chain link fence.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

1. Name of F	Property	(indicate preferred n	ame)	-			
historic	Saint John's Eva	ingelical Lutheran Church (p	referred)				
other	Saint John's Lut	heran Church					
2. Location							
street and number	8808 Harford R	oad			=	not for p	ublication
city, town	Parkville					vicinity	
county	Baltimore Coun	ty					
3. Owner of	Property	(give names and mailing	addresses o	f all owners	s)		
name	Saint John's Eva	ingelical Lutheran Church					
street and number	8808 Harford R	oad			telephone	Not Avail	able
city, town	Baltimore		state M	D	zip code	21234	
Contri Contri Deterr Deterr	buting Resource ir buting Resource ir mined Eligible for t mined Ineligible for ded by HABS/HAE ic Structure Repor	n National Register District in Local Historic District the National Register/Marylar in the National Register/Marylar ER t or Research Report at MHT	nd Register and Register				
6. Classifica							
Categorydistrict _X_building(s)structuresiteobject	OwnershippublicX_privateboth	Current Function agriculturecommerce/tradedefensedomesticeducationX_funerarygovernmenthealth careindustry	X_religion social transp work ir	tion/culture ortation ortogress	1 2 Number o	None 1 1 1 1 1 1 1 1 1 1 1	contributing buildings sites structure objects Total ng Resources ne Inventory

_	-				
1	I)e	SCI	rın	tic	nn.
	-	50			

Inventory No. BA - 866

Condition

excellent	deteriorated
X_good	ruins
fair	altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

This Gothic Revival church, built circa 1950, fronts southeast with a cemetery and a paved parking lot to the north. The random, ashlar-cut stone foundation supports a random Ashlar-cut stone structural system. Standing one-and-a-half stories tall and three bays wide, the church has a front gable roof with slate tiles and a parged concrete chimney on the exterior end. In the gabled parapet of the façade is a stained glass, pointed arch window with wood tracery placed above three, grouped pointed-arch stained-glass windows. The spandrel between the windows consists of stone quatrefoils. The windows have molded wood surrounds, a pointed-arch stone lintel, and stone sills. Flanking this large window are two, pointed-arch stained-glass windows with metal, diamond panes and stone surrounds. Projecting to the east are two wings, the smaller of which contains the main entry. The entry features two paneled double-leaf doors made with beaded vertical board. Each set of doors has wood surrounds, a pointed-arch, stone lintel, and a molded, stone tympanum. In the gable end of the wing's parapet is a metal, louvered vent with stone surrounds. In the hyphen connecting the two wings are three stained glass metal windows rectangular in shape that are grouped with a stone lintel containing three, pointed arches. The larger wing has eight paired 1/1 windows with square-edged wood surrounds, stone sills, and jack arch, stone lintels on the southeast elevation. Differences in building materials suggest that the main block was built in two stages with an additional four-bays in depth added to the original four bays. The southwest elevation of the original church has a random, Ashlar-cut stone belfry projecting from the roof in a gabled parapet. Including all eight bays of the main block and the addition, there are seven stained-glass metal windows rectangular in shape with stone surrounds, sills, and lintels. Also, there are twelve 1/1 windows with square-edged wood surrounds and stone lintels and sills. There are three flush metal doors that are single-leaf with one-light and molded wood surrounds. The rear of the addition is parged concrete with three pointed-arch stained glass windows grouped in a large pointed-arch stone lintel with parged concrete spandrels and stone sill.

Located to the north of the church is a cemetery enclosed in a chain link fence. Surveyed from the parking lot, the cemetery appears to have approximately thirty-two rows of 200 headstones facing southeast. These mostly upright granite and marble markers range in date from 1833 to 2000. Some of the family names within this sloping cemetery are Maria, Foard, Dorr, Geddis, and Todd.

Located to the northwest of the church are offices in the Smith Building built circa 1960. This one-story building clad in stucco has a hipped roof with asphalt shingles. There is an exterior-end parged chimney and a vinyl, 1/1 window with vinyl surrounds and a parged sill. The building features three entrances: two flush single-leaf doors made of metal and a double-leaf metal door that is flush with lights.

8. Signific	ance			Inventory No. BA- 866
Period	Areas of Significance	Check and j	ustify below	
1600-1699 1700-1799 X 1800-1899 X 1900-1999 2000-	agriculture archeology X architecture art commerce communications community planning conservation	 economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement 	health/medicine industry invention landscape archite law literature maritime history military	performing arts philosophy politics/government ecture X religion science social history transportation other:
Specific dates	1950-present		Architect/Builder	Unknown
Construction da	ates 1950 ca., 1970 ca.			
Evaluation for:				
	National Register		Maryland Register	Xnot evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

Constructed in the Gothic Revival style, St. John's Lutheran Church dates to a mid-20th century period of suburbanization on the east side of Baltimore City. This stretch of Harford Road was already developing at a fast pace by 1850, and Lavender Hill Post Office, in which the church was erected, was a thriving community. With the growth and expansion of Baltimore City, the community of Lavender Hill has become a suburb of the city and the surrounding built environment indicates this mid-20th century period of development. The stone church was constructed in the Gothic Revival style and represents a resurgence of interest in this style of architecture in the mid-20th century. The Gothic Revival style abstracted elements from Gothic cathedrals of medieval Europe, primarily those of England and France. Representative of this style are the building's pointed-arch windows and wall buttresses.

¹ J.C. Sidney, Map of the City and County of Baltimore, Maryland, from Original Surveys (Baltimore, MD: James M. Stephens, 1850).

9. Major Bibliographical References

Inventory No. BA- 866

Atlas of Baltimore County, Maryland. Philadelphia, PA: G. M. Hopkins, 1877.

Baltimore County Historic Inventory.

Brooks, Neal A. and Eric G. Rockel. A History of Baltimore County. Towson, MD: Friends of the Towson Library, Inc., 1979. Map of Baltimore County. Philadelphia, PA: G. W. Bromley, 1915.

Scharf, J. Thomas. History of Baltimore City and County From the Earliest Period to the Present Day: Including Biographical Sketches of Their Representative Men. Philadelphia, PA: Louis H. Everts, 1881. Reprinted by Higginson Book Company, Salem, MA.

Sidney, J. C. Map of the City and County of Baltimore, Maryland, from Original Surveys. Baltimore, MD: James M. Stephens, 1850.

10. Geographical Data

Acreage of surveyed property _	4.227 Acres		
Acreage of historical setting	Unknown	====9	
Quadrangle name	Towson	Quadrangle scale:	1:24,000
Constitution of the Consti			

Verbal boundary description and justification

Since its construction circa 1950, St. John's Evangelical Lutheran Church has been associated with the 4.227 acres of land known as tax parcel 606 of map 71 located in the Baltimore County Tax Assessor's office.

11. Form Prepared by

name/title	A. McDonald and A. Didden, Architectural Historians		
organization	EHT Traceries, Incorporated	date	May 21, 2001
street & number	1121 5th Street NW	telephone	202.393.1199
city or town	Washington	state	DC

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.


The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:


Maryland Historical Trust DHCD/DHCP 100 Community Place Crownsville, MD 21032-2023 410-514-7600


CEMETERY RESOURCE SKETCH MAP BA- 866 ST. JOHN'S EVANGELICAL LUTHERAN CHURCH 8808 HARFORD RD ISTORY FLAT PARKVILLE, MD BALTIMORE COUNTY NOT DRAWN TO SCALE PARKING LOT 1-STORY 2-STORY FLAT Fince 2-STORY Chain Unk 1-STORY FLAT 1 1/2 STORY □ SIGN

HARFORD ROAD



BA- \866
St. John's Evangelical Lutheran Church
8808 Harford Road (MD 147)
Baltimore County, MD: Towson
Parkville, Tax Parcel Map
Map 71, Parcel 606
EHT Traceries, Inc. 2006







BA-866 (10F5)
ST. JOHN'S LUTHERAN CHURCH
8808 HARFORD ROAD
BALTIMORE COUNTY, MARYLAND
EHT TRACERIES
APRIL 2006
MD SHPO
SOUTH ELEVATION, LOOKING MORTH



BA-866 (2 OF S)
ST. JOHN'S LUTHERAN CHURCH
8808 HARFORD ROAD
BALTIMORE, COUNTY, MARYLAND
EHT TRACERIES
APRIL 2006
MD SHPO
EAST ELEVATION, LOOKING WEST



BA-866 (3 OF S)

ST. JOHN'S LUTHERAN CHURCH

8808 HARFORD BOAD

BALTIMORE COUNTY, MARYLAND

EHT TRACERIES

APRIL 2006

MD SHPO

WEST ELEVATION, LOOKING EAST



BA-866 (4 OF S)

ST. JOHN'S LUTHERAN CHURCH

8808 HARFORD ROAD

BALTIMORE COUNTY, MARYLAND

EHT TRACERIES

APRIL 2006

MD SHPO

NORTH ELEVATION, LOOKING SOUTH WEST



BA-866 (5 OF 5)
ST. JOHN'S LUTHERAN CHURCH
8808 HARFORD ROAD
BALTIMORE COUNTY, MARYLAND
EHT TRACERIES
APRIL 2006
MD SHPO
NORTH ELEVATION AND REAR BUILDING, LOOKING SOUTH



8808 HARFULDROAD BALTIMORE COUNTY, MID TRACERIES

BALTIMORE

3/2001

mo-stro

E CORNER

BA-866



BA- 866 8808 HARFORD ROAD BALTIMORE COUNTY, WO THERES

MO-SHPU

N COENER



BA-0866
8808 HARFOLD BOAD
BALTIMUNE
BALTIMUNE
BALTIMORE LOUNTY, ND
THA CERLES
3/2001

mo-steo

MEDERNER

3044



BA- 0866 8868 HARFORD ROAD BALTIMORE CONTYIND TRALERIES 3/2001

MO-SHPD

CEMETERY

Road. Erroneously assigned an Inventory Number. Not antique. The frame chapel of 1887 had been removed.